


(A) Make a drawing of the holes from a given specifications. Draw the front view in broken-out section.



(B) Make a drawing of the holes from a given specifications. Draw the front view in broken-out section.

